Repair Estimate

Service Advisor

PREPARED FOR



Date 08/12/2024 03:25 PM 2024 Acura INTEGRA

VIN

Mileage 25,325 RO# 24215

| Service Name | Price |
|---|----------|
| [Primary]: 91ACZ222 : 48000 KM ACURA RECOMMENDED SERVICES **MAINTENANCE MINDER A (0W-20) | \$70.40 |
| [Primary]: NOC : NO OUTSTANDING RECALLS AS PER ACURA CANADA C/S: NO OUTSTANDING RECALLS AS PER ACURA CANADA | \$0.00 |
| [Primary]: W : COMPLIMENTARY EXTERIOR CAR WASH C/S: COMPLIMENTARY EXTERIOR CAR WASH | \$0.00 |
| [Primary]: H199 : MORE INFORMATION 2 C/S: CLIENT IS PROVIDING THERE OWN OIL IN BACK SEAT | \$0.00 |
| [Primary]: UBER : CUSTOMER WOULD LIKE AN UBER RIDE. CUSTOMER REQUESTED A RENTAL | \$0.00 |
| [Primary]: COMP : ACURA COMPLIMENTARY VEHICLE MULTI-POINT INSPECTION ACURA COMPLIMENTARY VEHICLE MULTI-POINT INSPECTION | \$0.00 |
| *Cabin Air Filter Replacement: AIR AND POLLEN FILTERS | \$221.87 |
| *Alignment: FOUR WHEEL ALIGNMENT(\$169.95), RECOMMENDED TO ENSURE PROPER TIRE WEAR AND CORRECT ALIGNMENT ANGLES | \$169.95 |
| [Other]: FRONT AND REAR BRAKE SERVICE | \$362.61 |
| *Brake Flush: REPLACE BRAKE FLUID | \$201.30 |
| *Tire Rotation: SUB SYMBOL 1 - ROTATE TIRES | \$95.00 |
| Printed on August 12, 2024 | |
| Quote expires on September 11, 2024 | |

Subtotal \$1121.13 **Total** \$1121.13

Southview Acura

Southview

9820 34th Avenue Northwest Edmonton, AB T6E 6L1

8554630058